



[Sign in](#) [Create free account](#)



Search over 62,300 items for sale...

Search

[Browse by category](#) ▼

[Auctions](#) ▼

[How it works](#) ▼

[Financing](#)



Auction Today!

START BIDDING

[Home Page](#) / [Trucks & Trailers](#) / [Humvees](#) / [4 Door Hard Top w/Slant Back](#)

[Search for other Humvees items](#)

[View all U.S. Marine Corps items](#)



2003 AM General M1045A2 HMMWV 4 Door Hard Top w/Slant Back

ITEM NUMBER	875346
LOCATION	Albany, Georgia, United States. 31705
SOLD ON	3/7/18
WINNING BID	US \$35,700
# OF BIDS	247 View Bid History

SOLD!

ITEM DETAILS

MILEAGE	90 Miles
VIN	206XXX
6.5L Diesel Engine, Automatic Transmission w/Park & Overdrive, 4x4, 10,300 lb. GVWR, Front Winch, 4 Hard Doors, Hard Top, Slant Back, Tow Carrier Body, 37x12.50R16.5 Tires.***No further demilitarization is required. The HMMWV is available for pick up as shown.*** The Humvee sells with a clean SF97.	



Inspected by IronPlanet.

Your purchase is protected by our **IronClad Assurance**.



See Full Gallery (46 - photos & videos)

Print Email Shar Shar Shar

Recommendations For You Search all



2003 Freightliner FL106 Roll Off Truck
Virginia (125 mi away)
US \$1,500



AM General M1043A2 HMMWV 4 Door Hard Top
Georgia (622 mi away)
US \$9,000



2004 AM General M1045A2 HMMWV 4 Door Hard Top
Georgia (622 mi away)
US \$8,500



2004 AM General M1045A2 HMMWV 4 Door Hard Top
Georgia (622 mi away)
US \$8,500



2002 AM General M1045A2 HMMWV 4 Door Hard Top
Georgia (622 mi away)
US \$9,000



2000 AM General M1 HMMWV 4 Door Hard
Georgia (622 mi away)
US \$9,000

INSPECTION REPORT

General Appearance
Drivetrain

Control Station
Chassis

Engine

Please note that as the buyer, you are responsible for reviewing the entire inspection report when evaluating an item.






 Protected by IronClad Assurance®

GENERAL APPEARANCE

IMPORTANT INFORMATION

Export Control Compliance
Payment Details
Questions


Manifest
Shipping & Pick Up Details

DESCRIPTION	RATING	DETAILS
Paint		
Sheet Metal Condition		
Mirrors		
Exterior Lights	Operational	
 (5)		
CONTROL STATION		

Rental Fleet Reduction Sale March 14

View Items



**NOTICES & RESTRICTIONS**


Buyer is required to submit an End-Use Certificate (EUC) to be reviewed prior to removal of the item. First-time buyers of Demil B,D,E,F,Q, OR C items may experience an extended review period in the Trade Securities approval process.


GovPlanet is only permitted to sell Demil B,D,E,F,Q, OR C items within the United States and only to U.S. citizens.

Security requirements and restrictions may apply at the time of pickup. **See shipping terms for details.**


Specific terms & conditions apply. **See details.**

Items may be subject to U.S. export controls. **See details.**












**MANIFEST**

NSN/LSN	Demil code ¹	Description (DTID) 
	Q	609245

¹DLA Disposition Services Demilitarization Codes. Click on code for more information.

**PAYMENT DETAILS**

- Within **3 business days** after the auction, the buyer must submit full payment, including applicable taxes and fees to avoid **late fees**. For this item, payment is due on or before March 12.

DESCRIPTION	RATING	DETAILS
Glass Condition		
Seating		
Seat Belts	Operational	
Steering Control		
Drivetrain Controls		
Master Cylinder/Brake Control		
Park Brake	Stopped the vehicle while rolling	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Oil Pressure	55 PSI	
Warning Lights	Operational	
Gauges	Operational	
Odometer	90.2 Miles - IronPlanet makes no guarantees as to actual hours/miles; we can only report what can be visually observed.	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	
 (14)		
ENGINE		

- Buyer must pay a **transaction fee**, based on the final selling price:

FINAL SELLING PRICE	TRANSACTION FEE
Above \$1	10%

- Payment can be made by **wire transfer (recommended)** or credit card (**additional fee will apply**).
- If Selected, a Standard Form 97 (SF97) or Transferable titling document will be sent to the buyer by express mail or similar service. Typically buyers will receive their SF97 within 30 business days, although it can take up to 60 Business days, from the date the buyer takes possession of the item. Transferable titling documents typically take up to 30 business day after receipt of the SF97. Buyer is responsible for vehicle registration.
- **All bids are binding** and cannot be retracted. Failure to make full payment will result in a **Default Fee**.



SHIPPING & PICK UP DETAILS

- Buyer is **responsible for all costs** related to transporting the item.
- Item **must be picked up within 8 business days** of the auction, or the buyer will incur storage charges.

PICKUP TERMS

Failure to follow these terms may result in the seller turning away the attempt of your driver to pick up the purchased item(s).

Hours: Monday-Friday 8:00am-4:00pm

Call 24 hours in advance.

No Loading Dock, Ramps, or Forklift Available: Only RGN or trailers with ramps can be used to pick up this item at this location. Seller will not allow item to be loaded on a step-deck or flatbed trailer without the appropriate ramps.

Driver **MUST** bring a copy of the IronPlanet Item Release to pick the item up.














QUESTIONS

Customer Care Agents are available Monday to Friday, 6 a.m. to 5 p.m. (Pacific Time)

Phone 888-433-5426
+1-925-225-8600 (outside U.S.)

Fax 888-433-3467
+1-925-225-8610 (outside U.S.)

Email CustomerCare@ironplanet.com

DESCRIPTION	RATING	DETAILS
Emission Certification Label		Exempt 
Oil Pump/Tach Drive (behind doghouse cover)		
Blow by @ idle (subjective observation)		No noticeable vapor or pressure 
Starter		Operational
Fuel System		Operational 
Exhaust System		
Radiator		
Oil Leaks		None seen 
Fuel Leaks		None seen 
Cooling System Leaks		None seen 
Engine - Right Side		
Engine - Left Side		
Limited Function Check		The engine started and ran.
 (12)		
DRIVETRAIN		

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

DESCRIPTION	RATING	DETAILS
Transmission		Operational
Transfer Case		Operational
Steer Axle		
Rear Drive Axle		
Limited Function Check		The drivetrain was operational.



(4)

CHASSIS

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

DESCRIPTION	RATING	DETAILS
Steering Linkage		
Frame Condition		
Limited Function Check		The main chassis components functioned during a limited check.
Tire Condition		
Wheel Condition		
Wheel Studs, Nuts, Lugs		
Winch		Not operationally checked




(7)

Disputes:

This item is offered with **IronClad Assurance®** protection. With IronClad Assurance®, if a buyer discovers that the item is not substantially in the condition as represented in this inspection report, the buyer may submit a written dispute claim to IronPlanet. Following submission of a written dispute claim, IronPlanet will investigate the claim, re-inspecting the equipment item as necessary, and determine a fair and mutually beneficial resolution. Please note that IronPlanet inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not

designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

 **Need help?** [Contact Us](#)

 **North America**  **English** 

Company

About IronPlanet
About Ritchie Bros.
Careers
Blog
Terms & Conditions
Privacy
Site Map

Support

Contact Us
How to buy
How to sell
FAQs
RitchieSpecs

Our family of sites

GovPlanet
TruckPlanet
Asset Appraisal Services
Kruse Energy
Ritchie Bros. Auctioneers
SalvageSale
Mascus

Popular categories

Truck Tractors
Crawler Dozers
Dump Trucks
Equipment Trailers
Excavators
Agricultural Tractors
Flatbed Trucks

Stay connected



Download Our Mobile App



Copyright © 1999-2019 IronPlanet, Inc. All Rights Reserved. IronPlanet®, Asset Appraisal ServicesSM, TruckPlanet®, GovPlanet®, Kruse EnergySM, IronClad Assurance® and Auctions you can trust® are service marks of IronPlanet, Inc. All other marks and brands are the property of their respective owners.